

No.1094 15 October 2020

# JAPAN P&I NEWS

To the Members

#### **Recent Navigation Warnings of China Waters No.96**

We have obtained the recent navigation warnings of the China Waters issued by China MSA. Please see the following the free translations by the law firm in Shanghai, China, Sloma & Co.

///QUOTE///

# 1. Announcement on the Newly-established Isolated Danger Marker of the Sunken Ship "WANHUAI 1598" and Removal of Its AIS Virtual Navigation Mark

(Sloma Translation) JHT (2020) No.87 China MSA 14 September 2020

According to the beacon mark dynamic published by Tianjin Beacon Department of the Navigation Guarantee Center of North China Sea of MOT (JBJZ (2020) No.23), an Isolated Danger Marker will be set at 180 meters due west of the Sunken Ship "WANHUAI 1598" in Bohai waters and its AIS virtual navigation mark will be removed from now on, detailed parameters of the beacon are as follows:

Newly-established

Name	Location	Light	Shape	Structure	Type of	Remark
	(WGS-84)	Characteristics	Feature		Use	
Buoy Light of	38°42′27.15″N/	FL (2)	Black-Red-Black	Steel	Isolated	Newly-
the Sunken	119°32′35.85″E	White Light	Pillar Buoy with	buoy	Danger	established
Ship		5s	two black spherical	light	Marker	
"WANHUAI			top marks			
1598"						

Removed

Name	MMSI	Location	Launch	Type of Marker	Broadcast	Remark
		(WGS-84)	Pattern		Interval	
WANHUAI	994136409	38°42′27.15″N	Autonomous	Isolated Danger	3 minutes	Removed
1598		119°32′35.85″E	and	Marker		
WRECK PA			Continuous			

### 2. Fault Repair Project of the Submarine Cable of Kenli Oil Field Group of Bonan Oil Field

(Sloma Translation) LHT(2020) No. 364 China MSA 12 September 2020

- I. Work Duration: 12 September 2020 30 December 2020.
- II. Work Unit: Offshore Oil Engineering Co., Ltd.
- III. Work Boat: "Hai Jian 52" and "Hai Yang Shi You 925"
- IV. Work Site:
  - Waters between Submarine Cable KL35-2 CEPA and KL3-2 CEPA in Kenli Oil Field Group: centered by 38° 01′ 37.1306″ N/119° 36′ 15.6829″ E, with a radius of 500 meters;
  - Waters between Submarine Cable KL10-1 CEPA and KL3-2 CEPA in Kenli Oil Field Group: a rectangular water area whose central axis is bounded by Point A (37° 56′ 27.1091″ N/119° 32′ 43.0581″ E) and Point B (37° 56′ 25.9693″ N/119° 32′ 43.7530″ E) with a length of 4000m and a width of 1000m.
- V. Work Mode: Fault Submarine Cable Repair Operation.
- VI. Cautions:
  - 1. The workboats should exhibit corresponding signals as regulated, strengthen duty, keep watch on VHF 24 hours a day, contact with passing vessels without delay to ensure safety.
  - 2. Passing vessels should strengthen lookout, strengthen contact with workboats, sail cautiously, pay attention to identification of the signals and keep a safe distance with the workboats.

## 3. Fault Emergency Repair on S4 of the APG Submarine Optical Fiber Cables in Changjiang Estuary

(Sloma Translation) HHH (2020) No. 390 China MSA 21 September 2020

- I. Work duration: 21 September 2020 20 November 2020, day-night operation.
- II. Work site: Water areas near Lvhuashan of Changjiang Estuary, bounded by the following four points in order:
  - A, 30°52′29.94″N/122°20′08.82″E;
  - B、30°52′50.16″N/122°33′15.12″E;
  - $C_{30}^{\circ}52'17.82''N/122^{\circ}33'15.12''E$ ;
  - D、30°51′57.12″N/122°20′08.88″E.
- III. Work mode: Workboat "Feng Yang Hai Gong" (LOA: 57.6m, molded breadth: 22.0m) or "Tian Yi Hai Gong" (LOA: 76.0m, molded breadth: 22.0m) will detect the fault location, salvage and cut off the defective cable, splice, lay and repair the cable, bury and repair the cable along route of S4 of APG submarine optical fiber cable in the work site. During the operation, the navigation speed of the workboat is relatively slow.
- IV. Cautions:
  - 1. The workboat should exhibit lights and shapes as regulated, display visible marks where the anchors enter the waters during daytime, light up the location at nighttime, keep AIS on normally.
  - 2. The workboat should strengthen watch on VHF16 and report movement of the vessels and contact with the passing vessels voluntarily and implement security works.
  - 3. Passing vessels should keep a safe distance with the workboat, sail cautiously and pay attention to the avoidance.
  - 4. The operation should be suspended in case the wind force is greater than 7 or the visibility is less than 1 sea mile.

Fault Emergency Repair on S3 of the NCP (New Crossing-Pacific Cable System) in East China Sea (Sloma Translation)
HHH (2020) No. 399
China MSA 21 September 2020

- I. Work duration: 22 September 2020 21 November 2020, day-night operation.
- II. Work site: Water areas of East China Sea outside Changjiang Estuary, bounded by the following four points in order:
  - A、30°58′02.4″N/122°50′22.8″E;
  - B、30°55′19.2″N/123°05′37.2″E;
  - C、30°54′45.6″N/123°05′39.6″E;
  - D、 30°57′30.0″N/122°50′22.8″E.
- III. Work mode: Workboat "MIRAERO" (Flag: Korean, LOA: 64.32m, molded breadth: 14.95m) or "CS FU HAI" (LOA: 105.8m, molded breadth: 20m) or "BOLD MAVERICK" (Flag: Panamanian, LOA: 105.8m, molded breadth: 20.0m) will detect the fault location, salvage and cut off the defective cable, splice, lay and repair the cable, bury and repair the cable along route of S3 of NPC in the work site. During the operation, the navigation speed of the workboat is relatively slow.
- IV. Cautions:
  - 1. The workboat should exhibit lights and shapes as regulated, display visible marks where the anchors enter the waters during daytime, light up the location at nighttime, keep AIS on normally.
  - 2. The workboat should strengthen watch on VHF16 and report movement of the vessels and contact with the passing vessels voluntarily and implement security works.
  - 3. Passing vessels should keep a safe distance with the workboat, sail cautiously and pay attention to the avoidance.
  - 4. The operation should be suspended in case the wind force is greater than 7 or the visibility is less than 1 sea mile.

#### DISCLAIMER

Please be advised that all the above navigation warnings were the important pieces selected from the official website of MSA China or that of other local MSAs. Sloma shall not be liable for the veracity of the above navigation warnings or the accuracy of their English and Japanese translations. Neither shall Sloma be liable for any person's/party's possible losses/damage which may result from relying upon the above navigation warnings.

Junmao Jiang Sloma & Co. 27 September 2020

///UNQUOTE///

Yours faithfully,

#### The Japan Ship Owners' Mutual Protection & Indemnity Association