

Attachment 7

															A	Attacl	hmen	t7œ	Jeck 2
		Organization						Baloty management system	1				1	Reference B				-	
18		esement table (Reference No. Real weather nerigation continuous		(pec) - I	ingine - Ce	toring)		Date and time of assessment : 1 Ap	rli 2021 to	MM DD					Work cel	ngery :	Routine	work	
	Participas :	ΔΔΔ, XXX, DDD					_	Place and name of work :									: Non-re	utino work	
	O Possibio haza	do and risk assessment			(C) Prevanities			D Provention/mitigation measures and post-measure risk a	Incorrect					Company essentment					
	Possible hazaro specific trouble	(because of~, by doing~, (causing))	Frequency of occurrence (a)	Severit Accident involving people	y (b) Other	Risk (a×b)	Risk level	Prevention/miligation measures	Frequency of occurrence (a)	Sevent Accident involving people	(b) Other	Risk (a×b)	Risk level	Frequency of occurrence (a)	Severi Accident involving people	0ther	Risk (a×b)	Risk level	Measures adopted
	When a naviga	ion light bulb went out, and was spare bulb, the spare bulb was also						la Essential measures) D. Physical countermeasures)											
5	out of order, TI	ere were no lights on,	2		2	4	м	5. Administrative countermeasured) Alwegys check the navigation lanterns, 14 Use of personal protective explanent)	2		1	2	u	2		1	2	ш	0
	(Hazard) Nervigo	ation lanterns						la. Encortial measured)											
6	The handrail w oneself up due to bruising and	ss damaged. When trying to hold to sweeing, this caused a fail which led broken bones.	з	з		9	м	 Physical contensatures) Immediately repair any damage, not just the handralls, in Aninistrative contensature) 	з	1		3	L	з	1		з	L	0
	Olazanti Harndr	als						(d. Use of personal protective equipment)											
7	means of supp	deck were not in place, As there is no ort in the event of a ship's motion, this crew to fall over or overboard.	4	5		20	нн	a. Easentid maauwa) B. Plysiad aautemaauwa) Ulfelines are to be set in place in rough weather, a. Administrative contenseauwa)	4	2		8	M	4	2		8	M	0
	Olazardi No ine	tallation of lifelines						If not described it in the procedures for dealing with rough weather, this is to be added, (4 Use of present protective explorent) If work must be carried out, a He belt connected to a lifeline is to be worn,	4	2		8	м	4	2		8	M	0
8	Shared inform rough weather drobbing object	stion) Failure to prepare a cabin for may result in injury from fails or 8.	з	2		6	м	 Exercise measured Popular assumemeasured Security of moving objects in the accommodation strengs and froms Athistoctic contemessured 	3	1		3	L	3	1		3	L	0
	Haand Movin	s objects in each room						The noom is always tidy. (4. Use of personal protective equipment)	Ŭ			>	-	Ŭ					
		Total (1~8) Nak level prjor te No.	24 8	18 5	14	88 8	\bowtie	Total (1~8) Risk lovel after countermeasure (Mg)	30 11	11 8	4	42	\ge	30 11	11 8	5	44	\ge	\ge
		Level (See the criteria)	3.0 3	3.6 4	3.5 4	11.0 12	Ĥ	Level (See the criteria)	3	1,4 2	1,0	3.8 6	M	11,0 3	1,4 2	1,3 2	4.0 6	M	\bowtie
inal isess nent	(Work possible?)	H → M (Yes) - No	The risk a	assessment	was carrie	d out as d	lescribed a	bove. As a result of the risk assessment, w	e herewith	confirm the	it safe wor	k is possib	le.	As asses: implemen	sed as abo ted.	ve. it is ou	hope that	counterme	asures b
	k after implementing r equal to "9".	countermeasures must be less		of the per	son respon	sible for th							Affiliation	and full na					
		Level assessed : LL Dele reviewd : DD/MM/2011	1~2 (V	(ery low)			L	S (Low) M 4~9 (Medium)		H	10~15		to of more	HH	16~20	(Very hig	H)		
-		Date remote : UV/mil/20TT				L		1975. 199. AA	ı				no. or your	De 1190	nn: A 100				

Fig. 25 Pre-work risk assessment table : Deck (Attachment 7)

In the example, eight risks have been identified, and we will now compare two of them with a significantly lower risk level.

If there is no countermeasure:

1 Possible hazards and risk assessment					
	Frequency of	Sever	ty(b)		
Possible hazard (because of \sim , by doing \sim , (causing specific trouble))	occurrence (a)	Accident involving people	Other	Risk (a×b)	Risk Level
Failure to plan for evacuation in a rough sea area, and failure to inform relevant parties of estimated arrival delays, resulting in confusion in rescheduling	2	_	4	8	м
(Hazard) No review of the voyage plan					



With an email or telephone call: 🦨

		Frequency	Sever	ty(b)		
	Prevention/mitigation measures	of occurrence (a)	Accident involving people	Other	Risk (a×b)	Risk Level
	(a. Essential measures)					
	(b. Physical countermeasures)					
1	(c. Administrative countermeasures)	 				
1	If there is a significant change in estimated time of arrival, this is to be reported immediately	2	-	1	2	LL
	(d. Use of personal protective equipment)					

Fig. 26 Risk assessment regarding countermeasures for rough weather on Deck (Example 1) (Extracted from Attachment 6 and 7)

Failure to plan for evacuation in a rough sea area, when the vessel actually enters a rough sea area, causing a significant delay to the estimated time of arrival (ETA), or where the vessel has made an evacuation plan but has not informed the related parties such as charterers etc. of the revised ETA, its failure to share information can cause confusion on shore, because it is assumed that the vessel will arrive as originally scheduled, and arrangements are made for entering port and cargo handling.

This may result in Off Hire Cases. If this were left as it is, the ship would need to be



contacted, so this is rated under Frequency as "2: infrequent", and Severity as "4" as it would interfere with the ship's operations. Multiplied by this, the risk level becomes 8:M. If this is communicated by email or phone call, the shore side will know what is going on and will be able to plan countermeasures in advance. This has been assessed as a reduction in severity to "2" with a risk level of 2:LL. It shows the importance of communication between ship and shore.

If there is no countermeasure:

	igl() Possible hazards and risk assessment					
		Frequency	Severi	ty(b)		
	Possible hazard (because of~, by doing~, (causing specific trouble))	of occurrence (a)	Accident involving people	Other	Risk (a×b)	Risk Level
4	Failure to close watertight doors, through which water can enter and cause wet damage. or, fractures caused from being caught in a watertight door.	4	5	4	20	нн
	(Hazard) Watertight doors					

With just a simple effort: 🖑

	② Prevention/mitigation measures and post-measure ris	k assessm	nent			
		Frequency	Severi	ty(b)	Risk	Dist
	Prevention/mitigation measures	ot occurrence (a)	Accident involving people	Other	(a×b)	Risk Level
	(a. Essential measures)					
4	(b. Physical countermeasures) Watertight doors are always to be securely closed and, if necessary, locked	2	1	1	2	LL
+	(c. Administrative countermeasures)					
	(d. Use of personal protective equipment)					

Fig. 27 Risk assessment regarding countermeasures for rough weather on Deck (Example 2) (Extracted from attachment 7)

Also, if the watertight doors at the entrance to the accommodation area are left open (or not closed properly), there is a possibility that water will enter through them. It is also possible that a person could get caught in a door and break a bone in the rush to close it in rough weather.

By identifying these risks, it is possible to avoid inadvertent memory lapse (errors in the memory process) by appointing (specifying) who is responsible for closing watertight doors (e.g. Boatswain (Bsn)) and having them report back explicitly when the work is completed.

Therefore, the risk level is assessed as 20: HH because of the potential for serious injury if left unattended. However, the risk level can be reduced to 2: LL by ensuring that the watertight doors are closed and reported, and that a supervisor, such as a Master or Chief Officer (C/O), visually inspects the site.

The closing work of watertight doors is one of the countermeasures for rough weather that we take for granted, but by practising a risk assessment and sharing the information with the crew, we can ensure that we don't carelessly forget to do it.

The vessel's pre-work risk assessment table is reported to the ship management company's responsible department, which reviews the ship's report and re-evaluates it each item. The results are then posted on the risk assessment table (Fig. 28) and fed back to the vessel with a decision on whether or not to proceed. In this example, the risk level has been reduced from HH to M, and although it is in the ALARP region, it has been determined a tolerable area.



Attachment 8




Fig. 28 Risk assessment regarding countermeasures for rough weather on Deck

Engine department (Figs. 29,30,31 and 32 Attachments 9, 10 and 11)

As with the Deck, a total of 8 risks were identified and the change in risk level between before and after measures are implemented is shown below. The severity of Personal injury has reduced from 12(H) to zero and Non-personal injury severity has reduced from 12(H) to 12(H) to

P&I Loss Prevention Bulletin

		Before measures are implemented	After measures are implemented
Mean value in Frequency of occurrence	:	3	3
Mean value in Severity (Personal injury)	:	4	-
Mean value in Severity (Non-personal injury)	:	4	2
Risk level (Personal injury)	:	12(H)	-
Risk level (Non-personal injury)	:	12(H)	6(M)

Attachment 10

_	Organization						Selviy management system						keterence N	•				
78	work risk assessment table (Reference No			naine • Ca												_	_	
	Reaction : Rough weather newlocition countermeasu Participal :	199	(Deck • E	ngine • Ce	rtoring)	-	Date and time of assessment : 1 A Place and name of work :	orii 2021 to	MM DD				-	Work cate	Golà :	Routine	work work	
						-	-									: Non-re	une won	
	O Peesible hazards and risk assessment	-	Search	- (2)		-	Provention/millgation measures and post-measure risk	Insurances	Severity	(5)			Company assessment					
	Possible hazard (because of ~, by doing~. (causing specific trouble))	Frequency of occurrence (a)	Accident Involving people	Other	Risk (a×b)	Risk level	Prevention/mitigation measures	Frequency d occurrence (a)	Accident involving people		Risk (a×b)	Risk level	Frequency of occurrence (a)	Accident involving people	Other	Risk (a×b)	Risk level	Measures adopted
	Fuel consumption increases due to increased						(a Eccential measures) (b. Physical countermeasures)											
5	navigation distance caused by give-way manoeuvres, resulting in fuel shortages.	з		4	12	н	(c. Administrative countermascurec) ROB is to be constantly monitorred,	3		1	3	L	3		1	3	L	0
	(Hazard) Fuel OI						(d. Use of personal protective equipment) (a. Essential measures)											
	Failure to inform crew not to use the lifts, following the triasering of safety devices caused by hull						a scentral measure() Switch off the power supply so that the lift cannot b used, 9. Physical conternessure()	1		1	1	LL	1		1	1	u.	0
6	agitation led to crew being confined.	1		2	2	LL	(c. Administrative countermeasures)											
	(Hazand) Lifts						(d. Use of personal protective equipment) (a. Essential measured)											
7	Overload operation of the main engine, surging and lacing of the supercharger (turbocharger) were not considered, so the main engine tripped.	3		з	9	м	 Physical contermentaries) Exchange information with the Mester, check the loa on the main engine and slow down if necessary. 	3		2	6	м	3		2	6	м	0
	Nuzani Supercharger (turbocharger)						(c. Administrative countermeasures) (d. Une of personal protective equipment) (a. Scenetick measured)											
	Clogging of the fuel system strainers due to hull agristion caused by rough weather, resulting in tripping of the main engine or generator						(a. Exercise menures) (b. Physical countermeasures) (c. Administrative countermeasures)											
8		4		5	20	н	Frequent strainer switching and cleaning before bein being exposed to rough weather and manoeuvring in rough weather. (4.0xx of personal potective equipment)	4		2	8	м	4		2	8	м	0
	(Nawd) Fuel system strainers		7					07		10		$ \rightarrow $	05		10			
	Total (1~8) Risk level prior to No. countermeasure (Avg.) Avg.	23	7	23 8	82 8	Ŕ	Total (1~8) Risk level prior to No. countermeasure (Avg.) Avg.	25 9	4	10	34 9	ð	25 9	4	10	34 9	\Leftrightarrow	Ś
	Level (See the criteria)	2.9 3	3.5 4	2.9	10,3	ĥ	Level (See the criteria	2.8	1.3	1.4	3.8 6		2.8 3	1.3	1.4	3,8 6	M	읒
Final ssess ment		The risk a	issessment	was carri	ed out as o	described	above. As a result of the risk assessment.	we herewit	o confirm that	it safe work	is possib	ole.	As assess be implem	ed as abo	ve. it is ou	r hope that	counterm	easures
he risk han or	k after implementing countermeasures must be less equal to "9".	Signature	of the per-	son respor	sible for t	he opera	ion: Master's signature :		-		4	Affiliation	and full na	me :				
		1~2 (V	ery low)			ι L	3 (Low) M 4~9 (Medula	ง	н	10~15 ()			HH	16~20		h)		
	Date revised : DD/MM/20YY						Rev. Ho. XX		_	_	He	o, of years	to be filed	for: X year	•		_	

Fig. 29 Risk assessment regarding countermeasures for rough weather e ect on Engine (Attachment 10)

As with the Deck, two items are extracted from the eight risks and compared.



Extracted from Attachment 9

If there is no countermeasure:

${f 0}$ Possible hazards and risk assessment					
	Frequency	Severi	ty(b)	D : 1	D : 1
Possible hazard (because of \sim , by doing \sim , (causing specific trouble))	of occurrence (a)	Accident involving people	Other	Risk (a×b)	Risk Level
Inadequate lubrication of main engine, generator and other equipment, and hull agitation causing low level alarm and tripping (emergency stop).	4	-	4	16	нн
(Hazard) Lack of lubricant					



		Frequency	Severi	ty(b)		
	Prevention/mitigation measures	of occurrence (a)	Accident involving people	Other	Risk (a×b)	Risk Level
2	(a. Essential measures)					
	(b. Physical countermeasures)					
	Check lubricant level and top up if necessary. Cleaning of strainer (including that of fuel system)	4	-	1	4	М
	(c. Administrative countermeasures)					
	(d. Use of personal protective equipment)					

Fig. 30 Risk assessment regarding countermeasures for rough weather e ect on Engine

(Example 1)

Extracted from Attachment 10 If there is no countermeasure:

	① Possible hazards and risk assessment					
		Frequency	Sever	ty(b)		Dist
	Possible hazard (because of \sim , by doing \sim , (causing specific trouble))	of occurrence (a)	Accident involving people	Other	Risk (a×b)	Risk Level
8	Clogging of the fuel system strainers due to hull agitation caused by rough weather, resulting in tripping of the main engine or generator.	4	-	5	20	нн
	(Hazard) Fuel system strainers					



Conduct watch more carefully;

		Frequency	Severi	ty(b)		
	Prevention/mitigation measures	of occurrence (a)	Accident involving people	Other	Risk (a×b)	Risk Level
	(a. Essential measures)					
	(b. Physical countermeasures)					
8	(c. Administrative countermeasures)					
0	Frequent strainer switching and cleaning before being exposed to rough weather and manoeuvring in rough weather.	4	-	2	8	М
	(d. Use of personal protective equipment)					

Fig. 31 Risk assessment regarding countermeasures for rough weather e ect on Engine (Example 2)

According to accident investigations by the Transport Safety Board, for example, cases of low lubricant levels being detected due to insufficient lubricant caused by hull movement in rough weather, or main engine tripping due to a clogged strainer, leading to accidents, have been reported. (See Loss Prevention Bulletin Vol.49 "Tips for Effective Engine Management and Maintenance")

In engineering departments on most vessels, these countermeasures are a normal part of an engineer's work when rough weather is expected. However, when a change in risk level is assessed numerically by risk assessment, the importance of the operation



becomes all the more apparent.

The company also receives the risk assessment reports from the Engineering Department. After re-evaluating them, they approve the implementation of all countermeasures and feed them back to the vessel (Figure 39).

Also in this example, the risk level has been reduced from HH to M, and although it is in the ALARP region, it has been determined a tolerable area.

Attachment 11




Fig. 32 Risk assessment regarding countermeasures for rough weather e ect on Engine Risk assessment table (Attachment 11)

Catering department (Figs. 33,34,35 and 36 Attachments 12, 13 and 14)

A total of seven risks were identified. The change in risk level between before and after measures are implemented is shown below. The severity of Personal injury has reduced from 15(H) to 4(M) and Non-personal injury severity has reduced from 15(H) to 4(M).

		Before measures are implemented	After measures are implemented
Mean value in Frequency of occurrence	:	5	4
Mean value in Severity (Personal injury)	:	3	1
Mean value in Severity (Non-personal injury)	:	3	1
Risk level (Personal injury)	:	15(H)	<mark>4(M)</mark>
Risk level (Non-personal injury)	:	15(H)	<mark>4(M)</mark>

Attachment 13




Fig. 33 Risk assessment regarding countermeasures for rough weather: Catering department (Attachment 13)

Now we compare the top two with a significant reduction in risk level out of the seven risks, as well as with Deck and Engine.



Extracted from Attachment 12

If not always behaving appropriately:

	\oplus Possible hazards and risk assessment								
		Frequency of occurrence (a)	Severity(b)			D . 1			
	Possible hazard (because of \sim , by doing \sim , (causing specific trouble))		Accident involving people	Other	Risk (a×b)	Risk Level			
1	By forgetting to turn off the cooking apparatus, a fire was caused by moving objects falling.	5	_	4	20	нн			
	(Hazard) Cooking utensil and moving objects								



By checking twice:

		Frequency of occurrence (a)	Severity(b)			
	Prevention/mitigation measures		Accident involving people	Other	Risk (a×b)	Risk Level
1	(a. Essential measures)					
	(b. Physical countermeasures) Fixing of moving objects	5	-	1	5	М
	(c. Administrative countermeasures) Always turn off cooking apparatus after use, not just in rough weather,	2	-	1	2	L
	(d. Use of personal protective equipment)					

Fig. 34 Risk assessment regarding countermeasures for rough weather: Catering department (Example 1)